

# **McCORMACK DECLARATION**

## **EXHIBIT S**

Overview for Complaint #:3163925 = RESOLVED

Page 1 of 1

[BIS Menu](#) | [Property Profile](#) | [Complaints](#) | [Complaint](#) | [Back](#)[FAQs](#) | [Glossary](#) Feb 1, 2007☒ [CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

## Overview for Complaint #:3163925 = RESOLVED

Complaint at: 97 QUENTIN ROAD

BIN: 3175390

Borough: BROOKLYN

ZIP: 11223

SETTLEMENT OF FDTN DUE TO ADJ EXCAVATION AND UNDERPINNING CRACKS EXTERIOR WALLS AND CELLAR  
 Re: SLAB. ADJ PROPRY 103 QUENTIN ROAD(NB 301658187) NO PERMIT FOR UNDERPINNING FILED UNDER 97  
 QUENTIN

Category Code: 73 FAILURE TO MAINTAIN

DOB District: N/A

Special District:

Assigned To: BROOKLYN BOROUGH OFFICE

Priority: C

Received: 07/22/2005 14:47

Block: 6622

Lot: 47

Community Board: 311

Owner: VASILIOS AFTOUSMIS/

Last Inspection: 08/02/2005 - - BY BADGE # 0763 POST KEVIN BROOKLYN

Disposition: 08/05/2005 - - C2 - INSPECTOR UNABLE TO GAIN ACCESS ON SECOND (2ND)  
 INSPECTION ATTEMPT

Disposition Entered By: HBE 08/05/2005

Comments: SITE CLOSED AND PADLOCKED

## Complaint Disposition History

Disposition Date	Code	Disposition	Inspection By	Date
07/29/2005	C1	INSPECTOR UNABLE TO GAIN ACCESS ON FIRST (1ST) INSPECTION ATTEMPT UNDERMINING OF FOUNDATIONS. NO CRACKS AT FOUNDATION EXTERIOR	1130 AGRAC	07/26/2005
08/04/2005	C1	INSPECTOR UNABLE TO GAIN ACCESS ON FIRST (1ST) INSPECTION ATTEMPT UNDERPINING OF FOUNDATIONS OF 97 QUENTIN CONFORMS TO DRAWING	1130 AGRAC	07/26/2005
08/05/2005	C2	INSPECTOR UNABLE TO GAIN ACCESS ON SECOND (2ND) INSPECTION ATTEMPT SITE CLOSED AND PADLOCKED	0763 POST	08/02/2005

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

[BIS Menu](#) | [Property Profile](#) | [Complaints](#) | [Complaint](#) | [Back](#)

Overview for Complaint #:31884 = RESOLVED

Page 1 of 1

[BIS Menu](#) | [Property Profile](#) | [Complaints](#) | [Complaint](#) | [Back](#)[FAQs](#) | [Glossary](#) Feb 1, 2007☒ [CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

## Overview for Complaint #:3198884 = RESOLVED

Complaint at: 103 QUENTIN ROAD

BIN: 3175389

Borough: BROOKLYN

ZIP: 11223

Re: ADJACENT PROPERTY IS NOT PROTECTED FROM FALLING DEBRIS, REAR YARD OF ADJACENT PROPERTY IS ALSO NOT PROTECTED FROM DANGEROUS CONSTRUCTION WORK AT ABOVE ADDRESS

Category Code: 03 ADJACENT BUILDINGS - NOT PROTECTED

DOB District: N/A

Special District:

Assigned To: BEST SQUAD

Priority: A

Received: 08/04/2006 08:24

Block: 6622 Lot: 45

Community Board: 311

Owner: 000000000000000 0 00000000000000000000

Last Inspection: 08/03/2006 -- BY BADGE # 1852 HILL EVEROL BROOKLYN

Disposition: 12/06/2006 -- L2 - FULL RESCIND OF STOP WORK ORDER

Disposition Entered By: GPH 12/06/2006 16:23:33

Comments: VIOLATION COMPLIED WITH AS PER INSPECTOR DAMIANO # 2233

Previous Violations: ECB: 34536177M -

## Complaint Disposition History

Disposition		Disposition	Inspection	
Date	Code		By	Date
08/05/2006	A3	STOP WORK ORDER VIOLATION ISSUED BUILDING ON LOT LINE STRUCTURE TO 5TH FLO NO PROTECTION PROV	1995 KRIKO	08/03/2006
12/06/2006	L2	IDED OVERHEAD ADJ PROPERTIES 1 VIOL SWO ISSUED FULL RESCIND OF STOP WORK ORDER VIOLATION COMPLIED WITH AS PER INSPECTOR DAMIANO # 2233	1852 HILL	08/03/2006

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

[BIS Menu](#) | [Property Profile](#) | [Complaints](#) | [Complaint](#) | [Back](#)